

**\*\* Please see footnote at bottom of page \*\***

Alpha by Model # Karcher GAS Models		PUMP OIL 15W-40		
		Change	oz	ml
G1800LB	1133-1240	No	3.38	100
G2000ET	1133-6200	No	3.38	100
G2000MK	1133-6210	No	3.38	100
G2000QT	1133-6010	No	3.38	100
G2200MTD	1133-1200	No	3.38	100
G2300IB	1133-2140	No	3.38	100
G2301LT	1133-2130	No	3.38	100
G2401OH	1194-5050	No	3.38	100
G2500HT	1194-3070	No	3.38	100
G2500LH (v1)	1194-4030	No	3.38	100
G2500LH (v2)	1194-4030	No	3.38	100
G2500OH	1194-5120	No	3.38	100
G2500PH (v1)	1194-4010	No	3.38	100
G2500PH (v2)	1194-4010	No	3.38	100
G2500VH (v1)	1194-4020	No	3.38	100
G2500VH (v2)	1194-4020	No	3.38	100
G2600OH	1194-5000	No	3.38	100
G2600OR	1194-5060	No	3.38	100
G2600PH (v1)	1194-4050	No	3.38	100
G2600PH (v2)	1194-4050	No	3.38	100
G2600VH (v1)	1194-4040	No	3.38	100
G2600VH (v2)	1194-4040	No	3.38	100
G2650HH	1194-5080	No	3.38	100
G2650OH (v1)	1194-5130	No	3.38	100
G2650OH (v2)	1194-5130	No	3.38	100
G2800OH (v1)	1194-5100	Yes	6.42	190
G2800OH (v2)	1194-5100	No	3.38	100
G3000BH (v1)	1194-6010	No	3.38	100
G3000BH (v2)	1194-6010	No	3.38	100
G3000OH (v1)	1194-5090	Yes	6.42	190
G3000OH (v2)	1194-5090	No	3.38	100
G3025BH	1194-6020	No	3.38	100
G3025OH	1194-5160	No	3.38	100
G3050OH (v1)	1194-5150	No	3.38	100

\*\* If your oil is a milky white or grayish in color, water has leaked through the piston oil seal (grooved ring) into the oil reservoir of the pump. Before ordering replacement seals, check on the condition of the bearings, pistons and pressure springs to ensure that these parts are not damaged and needing replacement.

**\*\* Please see footnote at bottom of page \*\***

Alpha by Model # Karcher GAS Models		PUMP OIL 15W-40		
		Change	oz	ml
G3050OH (v2)	1194-5150	No		
G4000OH	1194-8010	No	6.80	200
G4000RH (v1)	1810-4010	Yes	12.17	360
G4000RH (v2)	1810-4010	No	6.80	200
G4000SH	1810-4000	Yes	12.17	360
G4001RHca	1810-4020	Yes	12.17	360
HD2.3/23P	1575-1100			
HD2.3/23P (v1)	1575-3510			
HD2.3/23P (v2)	1575-3510	No	3.38	100
HD2.3/24P	1575-1000			
HD2.3/24P (v1)	1575-3500			
HD2.3/24P (v2)	1575-3500	No	3.38	100
HD2.3/26CV (v1)	1107-0770	No	3.38	100
HD2.3/26CV (v2)	1107-0770	No	3.38	100
HD2.5/24P (v1)	1575-1050	No	3.38	100
HD2.5/24P (v2)	1575-1050	No	3.38	100
HD2.5/27P	1575-1010			
HD2.5/27Pb (v1)	1575-1510			
HD2.5/27Pb (v2)	1575-1510			
HD2.5/30CH	1107-0780	No	3.38	100
HD2.6/26P (v1)	1575-1060	No	6.80	200
HD2.6/26P (v2)	1575-1060	No	6.80	200
HD2500G	1194-1120			
HD2500HK	1194-1150	No	3.38	100
HD2500MTD	1194-1140			
HD2525B	1194-1130	Yes	12.17	360
HD2600DK	1194-1220			
HD2700DB	1194-1160			
HD2700DH	1194-1170			
HD2700DH	1194-1230			
HD2700DH-QC	1194-1180			
HD2701DR	1194-2000			
HD3.1/31P (v1)	1575-1070	Yes	12.17	360

\*\* If your oil is a milky white or grayish in color, water has leaked through the piston oil seal (grooved ring) into the oil reservoir of the pump. Before ordering replacement seals, check on the condition of the bearings, pistons and pressure springs to ensure that these parts are not damaged and needing replacement.

**\*\* Please see footnote at bottom of page \*\***

Alpha by Model # Karcher GAS Models		PUMP OIL 15W-40		
		Change	oz	ml
HD3.1/31P (v2)	1575-1070	No	6.80	200
HD3.5/32Pb Cage (v1)	1575-2040			
HD3.5/32Pb Cage (v2)	1575-2040			
HD3.5/32Pb Cage (v3)	1575-2040			
HD3.7/35Pb (v1)	1575-1540			
HD3.7/35Pb (v2)	1575-1540			
HD3.7/35Pb Cage (v1)	1575-2050			
HD3.7/35Pb Cage (v2)	1575-2050			
HD3.7/35Pb Cage (v3)	1575-2050			
HD3.8/35P (v1)	1575-1040			
HD3.8/35P (v2)	1575-1040			
HD3000DH	1187-1150	Yes	12.17	360
HD3000DH-QC	1187-1160	Yes	12.17	360
HD3000G	1187-1110	Yes	12.17	360
HD3000MTD	1187-1140	Yes	12.17	360
HD3003B	1187-1120	Yes	12.17	360
HD3101DR	1187-1170	Yes	12.17	360
HD3500DB	1810-9980	Yes	12.17	360
HD3500DH	1810-9970	Yes	12.17	360
HD3500DH-QC	1810-9960	Yes	12.17	360
HD3500G	1810-9940	Yes	12.17	360
HD3501	1810-9990	Yes	12.17	360
HD3504B	1810-8050	Yes	12.17	360
HD3.6/40CH	1107-0790	No	6.80	200
HD3600DH	1810-9340	Yes	12.17	360
HD4.0/36P (v1)	1575-1080	Yes	12.17	360
HD4.0/36P (v2)	1575-1080	No	6.80	200
HD4.0/50Pb Cage (v1)	1575-2000			
HD4.0/50Pb Cage (v2)	1575-2000			
HD4.0/50Pb Cage (v3)	1575-2000			
HD4.5/50Pb Cage (v1)	1575-2010			
HD4.5/50Pb Cage (v2)	1575-2010			
HD4.5/50Pb Cage (v3)	1575-2010			
K12000G	1810-9830	Yes	11.80	350

\*\* If your oil is a milky white or grayish in color, water has leaked through the piston oil seal (grooved ring) into the oil reservoir of the pump. Before ordering replacement seals, check on the condition of the bearings, pistons and pressure springs to ensure that these parts are not damaged and needing replacement.

**\*\* Please see footnote at bottom of page \*\***

Alpha by Model # Karcher GAS Models		PUMP OIL 15W-40		
		Change	oz	ml
K12000G+	1810-9840	Yes	11.80	350
K14000G	1810-9890	Yes	11.80	350
K1500G	1133-1050	No	2.70	80
K1500Gca	1133-1120	No	2.70	80
K1800AB (v1)	1133-1220	Yes	12.17	360
K1800AB (v2)	1133-1220	No	3.38	100
K1800AB (v3)	1133-1220	No	3.38	100
K1800G (v1)	1133-1140	Yes	12.17	360
K1800G (v2)	1133-1140	No	3.38	100
K1800G (v3)	1133-1140	No	3.38	100
K1800Gca	1133-2090	No	3.38	100
K1800IB (v1)	1133-1210	Yes	12.17	360
K1800IB (v2)	1133-1210	No	3.38	100
K1800IB (v3)	1133-1210	No	3.38	100
K2200G (v1)	1133-1150	Yes	12.17	360
K2200G (v2)	1133-1150	No	3.38	100
K2200G (v3)	1133-1150	No	3.38	100
K2200IB (v1)	1133-2110	Yes	12.17	360
K2200IB (v2)	1133-2110	No	3.38	100
K2200IB (v3)	1133-2110	No	3.38	100
K2300G	1194-1100	No	3.38	100
K2301	1133-2130	No	3.38	100
K2400HB	1194-3030	No	3.38	100
K2400HH	1194-3010	No	3.38	100
K2400HHca	1194-3040	No	3.38	100
K2401HH	1194-3050	No	3.38	100
K3000G	1133-1100	No	2.70	80
K3000Gca	1133-1110	No	2.70	80
K3000Gca	1133-1170	Yes	12.17	360
K3300G	1133-1020	No	2.70	80
K3300G	1133-1030	No	2.70	80
K3300G	1133-1060	No	2.70	80
K3300GS	1133-1040	No	2.70	80
K4000G	1133-2010	No	3.38	100

\*\* If your oil is a milky white or grayish in color, water has leaked through the piston oil seal (grooved ring) into the oil reservoir of the pump. Before ordering replacement seals, check on the condition of the bearings, pistons and pressure springs to ensure that these parts are not damaged and needing replacement.

**\*\* Please see footnote at bottom of page \*\***

<b>Alpha by Model # Karcher GAS Models</b>		<b>PUMP OIL 15W-40</b>		
		<b>Change</b>	<b>oz</b>	<b>ml</b>
K4400G	1133-2080	No	3.38	100
K5000G	1133-1090	No	3.38	100
K5100Gca	?	No	3.38	100
K5800GHca	1194-1060	No	3.38	100
K6000GHca	1194-1090	No	3.38	100

\*\* If your oil is a milky white or grayish in color, water has leaked through the piston oil seal (grooved ring) into the oil reservoir of the pump. Before ordering replacement seals, check on the condition of the bearings, pistons and pressure springs to ensure that these parts are not damaged and needing replacement.